

## **Appendix D**

---

### **Site Photographs**

## SITE PHOTOGRAPHS

**Photo 1: Roadway looking west**



**Photo 2: North elevation**



**SITE PHOTOGRAPHS**

**Photo 3: Jammed joints (typical of both ends)**



**Photo 4: Typical spalling at curb**





**SITE PHOTOGRAPHS**

**Photo 5: Deformed railing**



**Photo 6: Broken post at southeast**



**SITE PHOTOGRAPHS**

**Photo 7: Severe spall at soffit (typical of soffit)**



**Photo 8: Beam end at southeast**





**SITE PHOTOGRAPHS**

**Photo 9: South exterior beam at east pier**



**Photo 10: Map cracking at west abutment**



**SITE PHOTOGRAPHS**

**Photo 11: West pier and soffit**



**Photo 12: Soffit at west truss**

