


CKL Collision Records Report



Produced on: 02/19/25

Produced by: Engineering - Technical Services

Filter Criteria: Reported collisions at intersection Jan 1, 2022 to Dec 31, 2024

Mary St at Adelaide St Collisions

ID 5086206

Report Num KL22001074 Classification 03 Property damage only Environment 01 Clear

Date/Time 2022-01-28T15:24: Impact Type 02 Angle Light 01 Daylight

00-05:00

X -78.744105 **Y** 44.343756

Driver Actions 01 Driving properly **Vehicle Manoevre** 01 Going ahead

08 Failed to yield right-of-way 01 Going ahead

RoadRd AliasRoad SurfaceRoad ConditionSurface ConditionsAlignmentMARY ST W<null>01 Asphalt01 Good01 Dry01 Straight on level

ADELAIDE ST S <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level

Police Statement

ID 5095221

Report Num KL22001578 Classification 03 Property damage only Environment 01 Clear

Date/Time 2022-02-11T11:50: Impact Type 02 Angle Light 01 Daylight

00-05:00

X -78.744105 **Y** 44.343756

Driver Actions 01 Driving properly **Vehicle Manoevre** 01 Going ahead

08 Failed to yield right-of-way 01 Going ahead

RoadRd AliasRoad SurfaceRoad ConditionSurface ConditionsAlignmentMARY ST W<null>01 Asphalt01 Good02 Wet01 Straight on level

ADELAIDE ST S < null> 01 Asphalt 01 Good 02 Wet 01 Straight on level

ID 5722613

Report Num KL22010133 Classification 03 Property damage only Environment 01 Clear

Date/Time 2022-09-20T18:02: Impact Type 05 Turning movement Light 01 Daylight

00-04:00

X -78.744081 **Y** 44.343656

Driver Actions 06 Improper turn **Vehicle Manoevre** 01 Going ahead

Driving properly 04 Turning left

Road Surface Road Condition Surface Conditions Road **Rd Alias Alignment** ADELAIDE ST S 01 Asphalt 01 Straight on level <null> 01 Good 01 Dry <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level MARY ST W

Police Statement

ID 6543968

Report Num RM23000035 Classification 03 Property damage only Environment 01 Clear

Date/Time 2023-02- Impact Type 02 Angle Light 01 Daylight

25T14:00:00. 000-05:00

X -78.744105 **Y** 44.343756

Driver Actions 01 Driving properly **Vehicle Manoevre** 01 Going ahead

08 Failed to yield right-of-way 01 Going ahead

Road **Rd Alias Road Surface Road Condition Surface Conditions Alignment** <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level MARY ST W ADELAIDE ST S <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level

ID 6751801

Report Num KL23008707 Classification 03 Property damage only **Environment** 02 Rain

Date/Time 2023-08-Impact Type 07 SMV other Light 01 Daylight

03T18:25:00. 000-04:00

Y 44.343678 X -78.74409

Driver Actions 07 Disobeyed traffic control Vehicle Manoevre 01 Going ahead

> Driving properly 01 Going ahead

Road Condition Surface Conditions Road **Rd Alias Road Surface Alignment** 01 Straight on level 189 KAWARTHA <null> 01 Asphalt 01 Good 02 Wet LAKES COUNTY

RD 19

ADELAIDE ST S <null> 01 Asphalt 01 Good 02 Wet 01 Straight on level

Police Statement

ID 7145794

Report Num KL24006261 **Classification** 03 Property damage only **Environment** 01 Clear

06 SMV unattended **Date/Time** 2024-05-Impact Type Light 08 Dark, artificia

25T23:40:00. vehicle

000-04:00

X -78.744105 **Y** 44.343756

Driver Actions <null> Vehicle Manoevre 01 Going ahead

> 10 Lost control 11 Parked

Rd Alias Road Surface Road Condition Surface Conditions Alignment Road <null> MARY ST W <null> <null> <null> <null>

ADELAIDE ST S 01 Good <null> 01 Asphalt 01 Dry 01 Straight on level

ID 7245567

Report Num KL24010305 Classification 02 Non-fatal injury Environment 01 Clear

Date/Time 2024-08- Impact Type 05 Turning movement Light 01 Daylight

20T11:26:00. 000-04:00

X -78.744105 **Y** 44.343756

Driver Actions 01 Driving properly **Vehicle Manoevre** 11 Parked

07 Disobeyed traffic control 04 Turning left <null> 01 Going ahead

Rd Alias Road Surface Road Condition Surface Conditions Alignment Road ADELAIDE ST S 01 Straight on level <null> 01 Asphalt 01 Good 01 Dry 01 Asphalt 01 Good 01 Straight on level MARY ST W <null> 01 Dry

Police Statement

ID 7258923

Report Num KL24010985 Classification 03 Property damage only Environment 01 Clear

Date/Time 2024-09- Impact Type 02 Angle Light 01 Daylight

04T16:30:00. 000-04:00

X -78.744105 **Y** 44.343756

Driver Actions 07 Disobeyed traffic control **Vehicle Manoevre** 01 Going ahead

01 Driving properly 01 Going ahead

Rd Alias Road Surface Road Condition Surface Conditions Road **Alignment** MARY ST W <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level ADELAIDE ST S <null> 01 Asphalt 01 Good 01 Dry 01 Straight on level

ID 7374494

X -78.744105

Classification 03 Property damage only **Environment** 02 Rain Report Num KL24014311

Date/Time 2024-11-Impact Type 02 Angle Light 08 Dark, artificia

19T18:41:00. 000-05:00

Y 44.343756

Vehicle Manoevre 01 **Driver Actions** 08 Failed to yield right-of-way Going ahead

> Driving properly 01 Going ahead

Road **Road Surface Road Condition Surface Conditions Alignment Rd Alias** 02 Wet 01 Straight on level ADELAIDE ST S <null> 01 Asphalt 01 Good

MARY ST W <null> 01 Asphalt 01 Good 02 Wet 01 Straight on level