

Collision Records Report

CKL Rd 121 at VCRT, Kinmount

- Filter: All reported collisions in view in latest available 36 months



● Reported Collision Location

1234567 Collision ID

Map produced by the City of Kawartha Lakes Engineering Department with data obtained under license. Reproduction without permission is prohibited.

The foregoing information is given for convenience only and it should be clearly understood that you must satisfy yourself as to whether the premises and the existing or proposed use thereof are, or would be, in conformity with all applicable by-laws and regulations of the municipality.

All distances and locations are approximate and are not of survey quality. This map is illustrative only. Do not rely on it as being a precise indicator of privately or publicly owned land, routes, locations or features, nor as a guide to navigate.





CKL Collision Records Report

Produced on: 03/27/24 Filter Criteria: latest available 36 months
Produced by: Engineering - Technical Services

Collision Data - CKL Rd 121 near Trail Crossing, Kinmount

ID 4981180

Report Num E211000218 **Classification** Property Damage only **Environment** Clear

Date/Time 2021-12-03T14:36:00-05:00 **Impact Type** SMV unattended **Light** Daylight

X -78.6554 **Y** 44.786

Road **Road Character** **Road Surface** **Road Condition** **Surface Conditions**

<null> <null> <null> <null> <null>

Police Statement

V1 reversing in private parking lot. V2 parked unattended. V1 reversed into V2 and fled scene.

ID 6105464

Report Num E221393815 **Classification** Property Damage only **Environment** Other

Date/Time 2022-11-23T11:15:00-05:00 **Impact Type** SMV other **Light** Daylight

X -78.6567 **Y** 44.7861

Road **Road Character** **Road Surface** **Road Condition** **Surface Conditions**

THE AVENUE <null> <null> <null> <null>

4131 Undivided- Asphalt Good Ice

COUNTY two-way

ROAD 121

Police Statement

V1 southbound on County Road 121.
V1 went into turn, hitting patch of ice.
V1 rear passenger tire mad contact with guard rail.

Collision Data - CKL Rd 121 near Trail Crossing, Kinmount

ID 6227401

Report Num E221474243 **Classification** Non-Fatal Injury **Environment** Other, Clear

Date/Time 2022-12-13T10:18:00-05:00 **Impact Type** SMV other **Light** Daylight

X -78.6573 **Y** 44.7861

Road	Road Character	Road Surface	Road Condition	Surface Conditions
4141 COUNTY ROAD 121	Undivided- two-way	Asphalt	Good	Wet
THE AVENUE	<null>	<null>	<null>	<null>

Police Statement

V1 ENTERING 40KM/H ZONE FROM 80KM/H ZONE
V1 ATTEMPTED TO TAKE CORNER
V1 ATTEMPTED TO BRAKE
V1 COULD NOT TURN
V1 WENT INTO GUARD RAIL
V1 HIT GUARD RAIL, FLIPPED OVER, AND LANDED ON ITS ROOF.

ID 6761804

Report Num E231063155 **Classification** Non-Fatal Injury **Environment** Rain

Date/Time 2023-08-07T09:03:00.000-04:00 **Impact Type** SMV other **Light** Daylight

X -78.6574 **Y** 44.7862

Road	Road Character	Road Surface	Road Condition	Surface Conditions
4109 COUNTY ROAD 121	Undivided- two-way	Asphalt	Good	Wet
The Avenue	<null>	<null>	<null>	<null>

Police Statement

V1 traveling SB, lost control of motorcycle on the corner, went down on its slide, sliding into the ditch.

Collision Data - CKL Rd 121 near Trail Crossing, Kinmount

ID 6828459

Report Num E231192409

Classification

Property Damage
only

Environment Clear

Date/Time 2023-09-
02T13:02:00.
000-04:00

Impact Type

SMV Other

Light Daylight

X -78.6578

Y 44.7869

Road	Road Character	Road Surface	Road Condition	Surface Conditions
CREGO LAKE RD	<null>	<null>	<null>	<null>
COUNTY ROAD 121	Undivided- two-way	Asphalt	Good	Dry

Police Statement

V1 merged into CR 503 after leaving Crego Street. V1 and V2 were in bumper to bumper traffic due to an event taking place in kinmount. V1 driver's foot slipped off of the brake pedal and went onto the gas and he collided into the rear of V2
